

Software release note

Simrad ME70 Scientific multibeam echo sounder

Software version

This document describes changes introduced with the following Simrad ME70 software version:

- ME70 SW 1.2.6.

Hardware configuration

The new software version is only valid implemented for a single computer configurations.

Software changes

Stability issue

A stability issue that was spuriously causing the system to stop with message “BDG9: INFO Warning Note buffer full Transceiver board in slot X” has been corrected.

Sector View on/off

This function has been removed from the Display menu.

Noise estimate values


These values are now updated in the Numerical view

Other minor bugs

Other minor bugs reported by users and/or detected during system testing have been corrected.

End user manuals

The ME70 Reference manual, Operator manual and On-line help have been updated. The manuals can be downloaded from www.simrad.com.



The Reference and Installation manuals are also available as separate websites on the following URLs:

- http://www.simrad.net/me70_ref_english/default.htm
- http://www.simrad.net/me70_ins_english/default.htm

Software availability

The operational software for the ME70 can be downloaded from the Simrad website using the log-in credentials offered to the individual ME70 customers.

The software can also be ordered on a relevant media using the following part number:

ME70 Processor Unit SW: **308940**

Software installation instructions

Software installation is made using a dedicated wizard.

Simrad

Kongsberg Maritime AS
Strandpromenaden 50
P.O.Box 111
N-3191 Horten, Norway

Telephone: +47 33 03 40 00
Telefax: +47 33 04 29 87
www.simrad.com
simrad.sales@simrad.com

SIMRAD